

SPINDLE SLICK

CONCENTRATED SPINDLE CLEANER

SPINDLE CLEANER is a water soluble, oil based, liquid formulation, designed to mix with water of any hardness.

It contains antistatic agents that help prevent the cotton from sticking on the spindles.

DIRECTIONS FOR USE

1. Fill cotton picker tank at least one-half full of water.
IMPORTANT: Water and cleaner will not mix if cleaner is poured in an empty tank first and water added later.
2. Agitate the water by operating the precision moistener control water system. This will recirculate the water back through the supply tank.
3. While the water is agitating, slowly add the **SPINDLE SLICK** to the water at a ratio of 10-20 oz. per 100 gallons of cleaner solution.
4. Finish filling tank with water while agitating continues. After tank is filled, allow agitation to continue for approximately five minutes.

NOTE 1: For best results, the mixture should be used within 24 hours. If mixture is allowed to stand for an extended time, agitate for several minutes before picking.

NOTE 2: Additional cleaner can be added for make-up in a tank already containing some previous mixture. If tank is less than half full, fill with plain water to half full. Follow mixing instructions and add cleaner at the correct ratio for the amount of water being added for make-up.



TRIANGLE CHEMICAL COMPANY
MACON, GEORGIA

CARDINAL CHEMICALS, INC.
KINSTON, NC